

Experian AutoCheck Report

Report run: 04/01/2026 17:27:25 EDT

2022 Chevrolet Trax LT

SUV 4D (1.4L I4 SMPI Gasoline)

VIN:	KL7CJPSM7NB535175
Class:	CUV - Compact
Country of Assembly:	South Korea
Vehicle Age:	4 year(s)
Estimated In Service:	07/01/2022
Last Reported Odometer:	109,536 (03/26/2026)



Vehicle Usage
Lease

88



93

AutoCheck Score

Similar vehicles usually range between 88 and 93

Vehicle History at a Glance



State Title Brand



Clean



Auction Brand / Issues



No Issue



Accident / Damage



Damage Reported



Open Recall Check



No Open Recalls



Insurance Loss / Transfer



No Issue



Odometer Check

Last reported odometer:
109,536 (03/26/2026)



No Issue



Certified Pre-Owned



No CPO Info Available



Service / Repair
2 Service Record(s)
Reported



No Issue



Additional History



No Issues Reported




This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

Accident & Damage



Damage Date	Damage Type	Severity
05/24/2024	Collision	Unknown

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



Unknown

Recommended Maintenance

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services



105000 Mile Service

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function
- Check engine coolant and washer fluid
- Check engine oil level and oil life percentage
- Check ignition transmission lock



112500 Mile Service

Not Yet Due

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function
- Check engine coolant and washer fluid
- Check engine oil level and oil life percentage
- Check ignition transmission lock



120000 Mile Service

Not Yet Due

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function
- Check engine coolant and washer fluid
- Check engine oil level and oil life percentage
- Check ignition transmission lock

- Check parking brake (and automatic transmission park mechanism, if applicable)
- Check starter switch
- Check tire inflation
- Check tires for wear
- Inspect brake system
- Inspect engine air cleaner filter
- Inspect engine cooling system
- Inspect exhaust system for loose or damaged components
- Inspect fuel system for damage or leaks
- Inspect power steering
- Inspect restraint system components
- Inspect sunroof track and seal (if equipped)
- Lubricate body components
- Replace windshield wiper blades
- Reset oil life system
- Rotate tires
- Visually check for any leaks or damage
- Visually inspect gas strut for signs of wear, cracks, or other damage
- Visually inspect halfshafts and drive shafts
- Visually inspect steering, suspension and chassis components

- Check parking brake (and automatic transmission park mechanism, if applicable)
- Check starter switch
- Check tire inflation
- Check tires for wear
- Inspect brake system
- Inspect engine air cleaner filter
- Inspect engine cooling system
- Inspect exhaust system for loose or damaged components
- Inspect fuel system for damage or leaks
- Inspect power steering
- Inspect restraint system components
- Inspect sunroof track and seal (if equipped)
- Lubricate body components
- Replace passenger compartment air filter
- Reset oil life system
- Rotate tires
- Visually check for any leaks or damage
- Visually inspect gas strut for signs of wear, cracks, or other damage
- Visually inspect halfshafts and drive shafts
- Visually inspect steering, suspension and chassis components

- Check parking brake (and automatic transmission park mechanism, if applicable)
- Check starter switch
- Check tire inflation
- Check tires for wear
- Inspect brake system
- Inspect engine air cleaner filter
- Inspect engine cooling system
- Inspect exhaust system for loose or damaged components
- Inspect fuel system for damage or leaks
- Inspect power steering
- Inspect restraint system components
- Inspect spark plug wires
- Inspect sunroof track and seal (if equipped)
- Lubricate body components
- Replace spark plugs
- Replace windshield wiper blades
- Reset oil life system
- Rotate tires
- Visually check for any leaks or damage
- Visually inspect gas strut for signs of wear, cracks, or other damage
- Visually inspect halfshafts and drive shafts
- Visually inspect steering, suspension and chassis components

Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2022 Chevrolet Trax LT (KL7CJPSM7NB535175) **Report Run Date:** 04/01/2026 17:27:25 EDT

2022 - Vehicle Prep and Other Pre-Titling Events

Location: EDEN PRAIRIE, MN

Preparation Date: 07/2022

Event Date	Location	Odometer	Data Source	Details
07/01/2022	EDEN PRAIRIE, MN	5	Service Record	Multiple Point Vehicle Inspection
07/05/2022	MN		Service Record	Vehicle Detailed Promotional Service Performed

2022 - Owner 1

Location: MN

Owned From: 07/2022

Usage: Lease

Event Date	Location	Odometer	Data Source	Details
07/08/2022	SHAKOPEE, MN		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
08/17/2022	MN	28	Motor Vehicle Dept.	Title(Title #:19681676-1) (Leased Vehicle)
04/05/2023	SHAKOPEE, MN		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
04/04/2024	SHAKOPEE, MN		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
05/24/2024	MN		State Agency	Left Side Impact with Another Vehicle(Case #: 1178860)



07/31/2024	SHAKOPEE, MN		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
04/08/2025	SHAKOPEE, MN		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
03/26/2026	MIDWEST REGION	109,536	Auto Auction	Reported at Auto Auction

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (KL7CJPSM7NB535175) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterm or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.

